


# Portable Appliance Testing Report




Presented to

**Rewind Disco & Photobooths**

27 Adelaide Street  
York  
YO23 1DL

Tested by

**Trinity Electrical**




Portable Appliance Testing Commencement Date  
**28/07/2017**

## PAT Test Summary



Rewind Disco & Photobooths

■ Appliances Passed    ■ Appliances Failed



iCertifi PAT Edition

Appliances tested for electrical safety in accordance with the IET code of practice for in service and inspection and testing of electrical equipment





Date Completed 28/07/2017

Certificate reference

PT7556102

# Portable Appliance Test (PAT) Completion Certificate



<b>DETAILS OF THE CLIENT</b> Client and address Rewind Disco & Photoboosths 27 Adelaide Street York Postcode: YO23 1DL		<b>ADDRESS OF TESTING</b> 27 Adelaide Street York Postcode: YO23 1DL	
<b>*ANY LIMITATIONS AGREED ON TESTING</b> *If any, reasons and with whom agreed		The Premises Are: Domestic <input checked="" type="checkbox"/> Commerical Industrial	
<b>DECLARATION</b> This is to certify the electrical appliances details in this certificate and record sheets have been tested for electrical safety in accordance with the IET code of practice for in service and inspection and testing of electrical equipment. It does not guarantee the correct operation of the appliance for any length of time. Users of the appliance should be aware of any fault or defect that may occur with future use. Any doubt regarding the safety or correct operation of the appliance, the device should be removed from service for further inspection by a competent person.		<b>ENGINEER, NAME &amp; SIGNATURE</b> Signature:  Name: TONY HADFIELD Date: 28/07/2017 	
<b>TESTING CARRIED OUT BY</b> Trading Title: Trinity Electrical Trinity Lodge Back Trinity Road Scarborough Telephone No: 0845 388 0971 Postcode: YO11 2TB Registration No: (if applicable) Branch No: (if applicable)		<b>PAT TESTER SERIAL NUMBER</b>  <b>NOTES</b> 	

**ANY FAILED APPLIANCES SHOULD BE REMOVED FROM SERVICE UNTIL THE DEFECT HAS BEEN RECTIFIED**

APPLIANCE SUMMARY FOR Rewind Disco & Photobooths 27 Adelaide Street York YO23 1DL

Total Appliances

32

Appliances Passed

32

Appliances Failed

0

PORTABLE APPLIANCE REGISTER

Appliance number	Appliance	Class	Location	Serial number/ID	Test Results				Visual check	Fuse rating (A)	Formal Visual Inspection (months)	Combined Inspection & Test (months)	Result
					Earth continuity test ( $\Omega$ )	Insulation Resistance M( $\Omega$ )	Load test (kVA)	Earth Leakage Test (mA)					
1	IEC Lead	2	Office	1	0.5	>200	N/A	N/A	✓	13	3	12	Pass
2	IEC Lead	2	Office	2	0.4	>200	N/A	N/A	✓	13	3	12	Pass
3	IEC Lead	2	Office	3	0.6	>200	N/A	N/A	✓	13	3	12	Pass
4	IEC Lead	2	Office	4	0.4	>200	N/A	N/A	✓	13	3	12	Pass
5	IEC Lead	2	Office	5	0.3	>200	N/A	N/A	✓	13	3	12	Pass
6	IEC Lead	2	Office	6	0.5	>200	N/A	N/A	✓	13	3	12	Pass
7	IEC Lead	2	Office	7	0.7	>200	N/A	N/A	✓	13	3	12	Pass
8	IEC Lead	2	Office	8	0.5	>200	N/A	N/A	✓	13	3	12	Pass
9	IEC Lead	2	Office	9	0.7	>200	N/A	N/A	✓	13	3	12	Pass
10	IEC Lead	2	Office	10	N/A	>200	N/A	N/A	✓	5	3	12	Pass
11	IEC Lead	2	Office	11	0.5	>200	N/A	N/A	✓	13	3	12	Pass
12	Laptop Power Supply	1	Office	12	N/A	N/A	N/A	N/A	✓		3	12	Pass
13	Laptop Power Supply	1	Office	13	N/A	N/A	N/A	N/A	✓		3	12	Pass
14	Lighting Effect	2	Office	14	0.11	>200	N/A	N/A	✓		3	12	Pass
15	IEC to IEC Lead	2	Office	15	0.5	>200	N/A	N/A	✓	N/A	3	12	Pass
16	IEC to IEC Lead	2	Office	16	0.4	>200	N/A	N/A	✓	N/A	3	12	Pass



Appliance number	Appliance	Class	Location	Serial number/ID	Test Results				Visual check	Fuse rating (A)	Formal Visual Inspection (months)	Combined Inspection & Test (months)	Result
					Earth continuity test ( $\Omega$ )	Insulation Resistance M( $\Omega$ )	Load test (kVA)	Earth Leakage Test (mA)					
17	Extension Lead	2	Office	17	0.9	>200	N/A	N/A	✓	13	3	12	Pass
18	Extension Lead	2	Office	18	0.6	>200	N/A	N/A	✓	13	3	12	Pass
19	Extension Lead	2	Office	19	0.6	>200	N/A	N/A	✓	13	3	12	Pass
20	Extension Lead	2	Office	20	0.8	>200	N/A	N/A	✓	13	3	12	Pass
21	Ciaat Brava Printer	1	Office	21	0.2	>200	N/A	N/A	✓	13	3	12	Pass
22	Ciaat Brava Printer	1	Office	22	0.2	>200	N/A	N/A	✓	13	3	12	Pass
23	Mitsubishi Printer	1	Office	23	0.4	>200	N/A	N/A	✓	13	3	12	Pass
24	Lighting Effect	2	Office	24	0.4	>200	N/A	N/A	✓	5	3	12	Pass
25	Lighting Effect	2	Office	25	0.9	>200	N/A	N/A	✓	5	3	12	Pass
26	Lighting Effect	2	Office	26	0.2	>200	N/A	N/A	✓	5	3	12	Pass
27	Lighting Effect	2	Office	27	0.6	>200	N/A	N/A	✓	5	3	12	Pass
28	Lighting Effect	2	Office	28	0.5	>200	N/A	N/A	✓	5	3	12	Pass
29	Lighting Effect	2	Office	29	0.5	>200	N/A	N/A	✓	5	3	12	Pass
30	Lighting Effect	2	Office	30	0.8	>200	N/A	N/A	✓	5	3	12	Pass
31	LED Light	2	Office	31	N/A	>200	N/A	N/A	✓	N/A	3	12	Pass
32	LED Light	2	Office		N/A	>200	N/A	N/A	✓	N/A	3	12	Pass

Appliance number	Appliance	Class	Location	Serial number/ID	Test Results				Visual check	Fuse rating (A)	Formal Visual Inspection (months)	Combined Inspection & Test (months)	Result
					Earth continuity test ( $\Omega$ )	Insulation Resistance M( $\Omega$ )	Load test (kVA)	Earth Leakage Test (mA)					
33	Citronic Audio Mixer	2	Office	33	N/A	>200	N/A	N/A	✓	5	3	12	Pass
34	RCF Speaker	2	Office	34	N/A	>200	N/A	N/A	✓	5	3	12	Pass
35	RCF Speaker	2	Office	35	N/A	>200	N/A	N/A	✓	5	3	12	Pass